

Version Upgrade Instructions on the Pluto System

Instructions:

The major version is the released unified version, including four minor versions, which give priority to the PlutoManager version.

Upgraded Version	Publishing Time	Revision and Addition	Compatibility with Previous Versions
<p>Major Version: V5.1.0</p> <p>Minor Versions:</p> <p>PlutoManager: V5.1.0</p> <p>PlutoSite: V5.1.0</p> <p>NovaLCT-Pluto: V5.1.0</p> <p>Versions of PlutoSystem</p> <p>PlutoSystem(PSD100) V5.1.0</p> <p>PlutoSystem(X65) V5.1.0</p> <p>PlutoSystem(PBOX150) V5.1.0</p> <p>PlutoSystem(PSD80) V5.0.1</p>	<p>2017.7.18</p>	<p>1. Revision</p> <ol style="list-style-type: none"> 1) The problem of unable to play the weather of China. 2) Fix the problem that the playback is lagging after playing the playlists with multiple pages for a period of time. 3) Fix the problem that the green light of FPGA is off after X65 or X60 is started. 	
<p>Major Version:V5.0.3</p> <p>Minor Versions:</p> <p>Version of PlutoManager:V5.0.3</p>	<p>2017.4.12</p>	<p>1. Revision</p> <p>(1) Remove the restriction on file size while upgrading font library of the PlutoManager.</p>	

<p>Version of PlutoSite: V5.0.3</p> <p>Version of NovaLCT-Pluto: V5.0.2</p> <p>Version of PlutoSystem: PlutoSystem(PSD100) V5.0.1 PlutoSystem(X65) V5.0.1 PlutoSystem(PBOX150) V5.0.1 PlutoSystem(PSD80) V5.0.1</p>			
<p>Major Version: V5.0.2</p> <p>Minor Versions:</p> <p>Version of PlutoManager: V5.0.2</p> <p>Version of NovaLCT-Pluto: V5.0.2</p> <p>Version of PlutoSite: V5.0.2</p> <p>Version of PlutoSystem: PlutoSystem(PSD100) V5.0.1 PlutoSystem(X65) V5.0.1 PlutoSystem(PBOX150) V5.0.1</p>	<p>2017.4.1</p>	<p>1. Revision</p> <ol style="list-style-type: none"> 1) Solve the problem including terminals reboot and parameters loss caused by setting brightness adjustment parameters on NovaCloud. 2) NovaLCT-Pluto solves the problem that modules of ICN2038 chips cannot display normally. 3) NovaLCT-Pluto solves the problem that modules of ICN2053 chips cannot display normally. 4) PlutoManager solved the problem that symbol "&" cannot be entered on the Sign list editing page. 	

PlutoSystem(PSD80) V5.0.1			
<p>Major Versions:V5.0.1</p> <p>Minor Versions: PlutoManager Version:V5.0.1 NovaLCT-Pluto Version:V5.0.1 PlutoSite Version:V5.0.1</p> <p>PlutoSystem:</p> <p>PlutoSystem(PSD100) V5.0.1 PlutoSystem(X65) V5.0.1 PlutoSystem(PBOX150) V5.0.1 PlutoSystem(PSD80) V5.0.1</p>	<p>2017.2.13</p>	<p>1.Revision</p> <p>(1)Reboot terminals after they are registered to the server of Nov aiCare, then terminals on the server of NovaiCare are always offline;</p>	
<p>Major Versions:V5.0.0</p> <p>Minor Versions: PlutoManager Version:V5.0.0 NovaLCT-Pluto Version:V5.0.0 PlutoSite Version:V5.0.0</p> <p>PlutoSystem:</p> <p>PlutoSystem(PSD100) V5.0.1 PlutoSystem(X65) V5.0.1 PlutoSystem(PBOX150) V5.0.1 PlutoSystem(PSD80) V5.0.1</p>	<p>2017.1.10</p>	<p>1. Additions</p> <p>(1) Sign list interface supports both Korean and Hindi; (2) PlutoManager supports the operation to select the NovaiCare server IP addresses; (3) PlutoManager supports Dutch; (4) PlutoManager supports single network card-to-multiple IP addresses; (5) PBOX150 supports the button-controlled switching;</p> <p>2. Optimizing</p> <p>(1) Optimize the display network connection;</p> <p>3. Revision</p> <p>(1) Revise the problem that weather information cannot be displayed; (2) Revise the problem that the PSD100 main board cannot display; (3) Revise the problem related to NovaiCloud supporting; (4) Revise the problem related to NovaiCare supporting; (5) Revise the problem about asynchronous card reboot</p>	

		<p>occurred in the process of character display;</p> <p>(6) Revise the problem about the LED display blackout in case of emergency insert play;</p> <p>(7) Revise the problem about the failed asynchronous card caused by test pattern modification in the process of video playing;</p> <p>(8) Revise the problem that only one transparent window is available while two are required after X65 reboot;</p> <p>(9) Revise the problem that the scrolling text play speed of PSD100 and that of both X65 and PBOX150 are not the same;</p> <p>(10) Revise the problem that NovaLCT-Pluto and PlutoManager are available by searching but cannot be connected;</p> <p>(11) Revise the problem that the asynchronous card cannot communicate with the screen after a long-term running;</p> <p>(12) Revise the problem that PSD100 main board loading and receiving card loading are not synchronous;</p> <p>4. Deleted Contents</p> <p>(1) Delete the automatic IP changing function of the asynchronous card;</p> <p>(2) Delete NovaiCloud and NovaiCare server parameter configuration function of NovaLCT-Pluto.</p>	
<p>Major Versions:V4.6.0</p> <p>Minor Versions:</p> <p>PlutoManager Version:V4.6.0</p>	<p>2016.3.22</p>	<p>1. Additions</p> <p>(1) Support X130;</p> <p>(2) Support PBOX110;</p> <p>(3) Support PSD80;</p> <p>(4) Support the synchronic</p>	

<p>NovaLCT-Pluto Version:V4.6.0 PlutoSite Version: V4.6.0</p> <p>PlutoSystem :</p> <p>PlutoSystem(PSD100)V4.5.2 PlutoSystem(X65) V4.5.2 PlutoSystem(X130)V4.5.4 PlutoSystem(PBOX110) V4.6.0 PlutoSystem(PSD80)V4.6.0</p>		<p>switching between audio and video of X65;</p> <p>(5) Support search configuration: when the terminal receives the search command for the first time, whether IP can achieve self-adaptation;</p> <p>(6) Support the running with administrator privileges by default after double clicking PlutoManager;</p> <p>(7) Support the running with administrator privileges by default after double clicking NovaLCT-Pluto;</p> <p>2.Optimizing</p> <p>(1) Sign interface text display;</p> <p>(2) Network search automatic connection mechanism;</p> <p>(3) HDMI recognition mechanism for optimizing X65.</p> <p>3.Revision</p> <p>Problems that China' s weather would not be displayed;</p>	
<p>Major Version:V4.5.3</p> <p>Minor Versions:</p> <p>PlutoManager Version:V4.5.3 NovaLCT-Pluto Version:V4.5.3 PlutoSite Version: V4.5.3 Android Phone APP: NovaSign V1.0 PlutoSystem Version: PlutoSystem(PSD100)V4.5.2 PlutoSystem(X65) V4.5.2</p>	<p>2015.12.10</p>	<p>1: Additions</p> <p>(1) Support smart brightness adjustment;</p> <p>(2) Support advanced settings of automatic brightness;</p> <p>(3) Add count up and count down to the timer media in edit playlist;</p> <p>(4) Add Canada to the weather media;</p> <p>(5) Add "Delete" key to the character editor in Sign list;</p> <p>2: Optimizing</p> <p>(1) The translation of character strings in the software;</p> <p>(2) The mechanism of search automatic connection;</p>	

		<p>3: Revision</p> <ul style="list-style-type: none"> (1) The characters can not be fully displayed in some types of fonts; (2) Some RSS web pages can not be played; 	
<p>Major Version:V4.5.2</p> <p>Minor Versions: PlutoManager Version:V4.5.2 NovaLCT-Pluto Version:V4.5.2 PlutoSite Version: V4.5.2 Android Phone APP: NovaSign V1.0 PlutoSystem Version: PlutoSystem(PSD100)V4.5.2 PlutoSystem(X65) V4.5.2</p>	<p>2015.9.2</p>	<p>1: Optimizing</p> <ul style="list-style-type: none"> (1) Optimized English translation for software; <p>2: Revision</p> <ul style="list-style-type: none"> (2) Display will can not communicate with Cloud server, afer configuring the address of Cloud server when the language is non-chinese; 	
<p>Major Version:V4.5.1</p> <p>Minor Versions: PlutoManager Version:V4.5.1 NovaLCT-Pluto Version:V4.5.1 PlutoSite Version: V4.5.1 Android Phone APP: NovaSign V1.0 PlutoSystem Version: PlutoSystem(PSD100)V4.5.2 PlutoSystem(X65) V4.5.2</p>	<p>2015.8.17</p>	<p>1: Additions</p> <ul style="list-style-type: none"> (1) Support configuration input source of X65/60 Box; <p>2: Optimizing</p> <ul style="list-style-type: none"> (1) Optimized English translation for software; <p>3: Revision</p> <ul style="list-style-type: none"> (1) Revise the problem that point detect exception when the chip is 5036; (2) Revise the problem that NovaLCT-Pluto search successful, but the connection failed; (3) Revise the problem that NovaLCT-Pluto search failed; (4) The word in editing area will be lost when the height of window and font size of 	

		combine text are identical; (5) Sign list will be exception when the media is picture with overlay text; (6) The combine text will be not transparent when you open the sign list with transparent combine text;	
<p>Major Version:V4.5.0</p> <p>Minor Versions:</p> <p>PlutoManager Version:V4.5.0</p> <p>NovaLCT-Pluto Version:V4.5.0</p> <p>PlutoSite Version: V4.5.0</p> <p>Android Phone APP:</p> <p>NovaSign V1.0</p> <p>PlutoSystem Version:</p> <p>PlutoSystem(PSD100)V4.5.0</p> <p>PlutoSystem(PCC80) V4.5.0</p>	<p style="text-align: center;">2015.6.17</p>	<p>1: Additions</p> <p>(1) Support Program production and transmission on the Android phone APP</p> <p>(2) PlutoManager and NovaLCT-Pluto support upgrading online;</p> <p>(3) Support some media background transparent;</p> <p>(4) Support GIF file playing;</p> <p>(5) Support Network messages (RSS);</p> <p>(6) Support Daylight Saving Time (DST);</p> <p>(7) Support NovaCloud and NovaiCare;</p> <p>(8) Sign media support the customized border;</p> <p>(9) Flash increase the broadcast time;</p> <p>(10) When program being sent, it support upgrading the unsupported fonts automatically;</p> <p>(11) Transparent text overlaying pictures and video support the alignment</p> <p>(12) Temperature and humidity media support decimal displayed and temperature compensation;</p> <p>(13) Digital clock and analog clock support Jet lag;</p>	<p style="text-align: center;">Compatibility</p> <p>(It suggests supporting the use of software, otherwise, this version added some new functions can't be used normally.)</p>

		<p>(14) The temperature support Fahrenheit and Celsius switch;</p> <p>(15) Static Text support Vertical Alignment;</p> <p>(16) Media support more effect;</p> <p>(17) Sign support adding media with dragging;</p> <p>(18) Sign support adding multiple Files;</p> <p>(19) Sign support customized window layout;</p> <p>(20) PlutoManager support Controlling LED screen regular boot and shutdown</p> <p>(21) PlutoManager support changing the default background of displays;</p> <p>(22) PlutoManager support the program lists with media;</p> <p>(23) PlutoManager support Spanish language and Traditional Chinese source;</p> <p>(24) NovaLCT-Pluto support row line detection within 20 groups of data;</p> <p>(25) New additional Driver IC: MBI5122 、 MBI5124 、 MBI5151、 MBI5152 、 MBI5153 、 MBI5155、 MBI5166 、 MBI5266 、 MBI6023、 MBI6030 、 MY9163 、 MY9221、 MY9262、MY9868、RT5924、</p>	
--	--	---	--

		<p>SM16136 、 SM16158 、 SUM2028、 SUM2032 、 TLC5929 、 TLC5958</p> <p>(26) NovaLCT-Pluto calibration: support SQLite data library;</p> <p>(27) Support more resolution: 1120*500 , 704*800 , 904*640</p> <p>2: Optimizing</p> <p>(1) Optimize the procedure of which program edited converted and sent;</p> <p>(2) Optimize the interface layout of Sign;</p> <p>(3) Optimize the parameters sent When single card selected of NovaLCT-Pluto</p> <p>(4) Optimize the networking of asynchronism card,IP configuration is needless;</p> <p>(5) Optimize the main interface layout of PlutoManager;</p> <p>(6) Optimize the schedule scan of Sign.</p> <p>3: Revision</p> <p>(1) Revise the problem that time of controller is reset to 2006.</p> <p>(2) Revise the problem that media of controller lost.</p> <p>(3) Revise the problem that files of controller damaged.</p> <p>(4) Revise the problem that controller being slow in boot-up when not connected to the Internet.</p> <p>(5) Revise the problem</p>	
--	--	---	--

		<p>software connected abnormally affected by firewall.</p> <p>(6) Revise the problem that Weather Forecast acquisition failure.</p> <p>(7) Revise the problem that to get the network time according Net failure.</p>	
<p>Major version:V4.4.0</p> <p>Sub-software versions: PlutoManagerversion: V4.4.0 NovaLCT-Pluto version: V4.4.0 PlutoSite version:V4.4.0 PlutoSystem version: PlutoSystem(PSD100)V4.4.1</p>	<p>2014.6.30</p>	<p>1:Additions:</p> <p>(1) Add an editing window for Sign program</p> <p>(2) Add media border effects</p> <p>(3) Add simplified text media</p> <p>(4) Play the onboard temperature and humidity sensor</p> <p>(5) Support online upgrading of multi-font files</p> <p>(6) The PCC80 supports online upgrading hardware program</p> <p>(7) Add the whole installation package. It contains the NovaLCT-Pluto and the PlutoManager</p> <p>(8) Add choices of the module color function on the point detect window</p> <p>(9) PlutoManager supports resources in Japanese</p> <p>2: Optimizing:</p> <p>(1) Optimize program editing, conversion and sending</p> <p>(2) Optimize the play effect of temperature and humidity</p> <p>(3) Optimize the view function of the desktop screenshot</p> <p>(4) Optimize network connections of the asynchronous cards</p> <p>(5) Optimize the play effect of analog clock</p> <p>(6) Optimize the software language in English</p> <p>(7) Optimize the problem of abnormal identification of USB disk</p>	<p>Compatible</p> <p>(You are recommended to use the sub-software in the versions listed in the Upgraded Version column. Otherwise, some new functions of the version cannot be normally used.)</p>

		<p>(8) Optimize PSD100 loading area</p> <p>3:Revision:</p> <p>(1) Revise the problem of failure in media conversion among different countries</p> <p>(2) Revise the problem of failure in media conversion among different countries</p> <p>(3) Revise the problem of appearing desktop backgrounds in a long-term playing of the asynchronous cards</p> <p>(4) Revise the problem of gaining a wrong time after starting daylight saving time</p> <p>(5) Revise the problem of abnormal saving of the correction data</p> <p>(6) Revise the problem of jump every 5 minutes in playing when the network cable is not connected</p> <p>(7) Revise the problem of abnormal play by the screen when the temperature is a negative value</p>	
<p>Major version:V4.3</p> <p>Sub-software versions: PlutoManagerversion: V4.3 NovaLCT-Pluto version: V4.3 PlutoSite version:V4.3.0 PlutoSystem version: WE60_101105_V4.3.0</p>	<p>2014.2.22</p>	<p>1:Additions:</p> <p>(1) Video, picture superimposed transparent static text</p> <p>(2) Manual, timing, automatic brightness adjustment</p> <p>(3) Asynchronous cards onboard wifi configuration</p> <p>(4) Synchronous play configuration</p> <p>(5)Asynchronous card connection parameters, authorization password, time synchronization mode configuration.</p> <p>(6) Set network time or computer time to asynchronous cards.</p> <p>2: Optimizing:</p> <p>(1) Optimize the single window, double window of video play quality.</p> <p>(2) support more video formats</p> <p>(3) Optimize the scrolling text play speed and play quality</p> <p>(4) Optimize media published</p>	<p>Compatible</p> <p>(You are recommended to use the sub-software in the versions listed in the Upgraded Version column. Otherwise, some new functions of the version cannot be normally used.)</p>

		<p>transmission speed and security</p> <p>3:Revision:</p> <p>(1) When editing text font size is calculated by pixels.</p> <p>(2) The issue of Static text cannot be played in different countries.</p> <p>(3) The issue of screen display red when the asynchronous card restarts.</p> <p>(4) The time losing issue of asynchronous card.</p> <p>(5) The left and right sound channel is played error issue for the asynchronous card.</p> <p>(6) The issue of lacking storage space for the asynchronous cards</p> <p>(7)The issue of camera collects image failed when correcting problems.</p>	
<p>Major version: V4.2</p> <p>Sub-software versions: PlutoManagerversion: V4.2 PlutoSite version: V4.2 NovaLCT-Pluto version: V4.0.4</p>	<p>2013.10.15</p>	<p>1. Addition:</p> <p>(1) Remote restart;</p> <p>(2) PlutoManagersetting the IP addressof asynchronous card ;</p> <p>(3) Font library upgrade;</p> <p>(4) Service pack upgrade;</p> <p>(5) Language update;</p> <p>(6) Support of the PSD100 cascade receiving card to 28 arrays;</p> <p>(7) Support of the PSD100 cascade receiving card to serial lamp panel;</p> <p>(8) Multi-screen configuration;</p> <p>(9) Power management of PSD100 board card</p> <p>2. Revision:</p> <p>(1) In the PlutoMbroadcasting management window, the acquisition time of page information does not change after the currently played information is successfully read.</p> <p>(2) The asynchronous card is set to the sending mode or relay. The window size changes to 0 after the</p>	<p>Compatible</p> <p>(You are recommended to use the sub-software in the versions listed in the Upgraded Version column. Otherwise, some new functions of the version cannot be normally used.)</p>

		hardware program is updated, and the terminal becomes abnormal after the broadcasting scheme is sent.	
<p>Major version: V4.0</p> <p>Sub-software versions: PlutoManager version: V4.0 PlutoSite version: V4.0 NovaLCT-Plutoversion: V4.0.3</p>	<p>2013.6.19</p>	<p>1. Addition:</p> <p>(1) Media display of temperature and humidity;</p> <p>(2) Firmware upgrade;</p> <p>(3) Sending card mode;</p> <p>(4) The PSD100 card supports data array exchange, special-shaped box and color rendition;</p> <p>(5) The server building scheme is added.</p> <p>2. Revision:</p> <p>(1) The software becomes abnormal when an incorrect license file is imported;</p> <p>(2) The problem that parameters cannot be saved when the box load is heavy has been resolved;</p> <p>(3) The screen goes blank when images are being captured during video playing.</p>	<p>Compatible</p> <p>(You are recommended to use the sub-software in the versions listed in the Upgraded Version column. Otherwise, some new functions of the version cannot be normally used.)</p>

XI'AN NOVASTAR TECH CO., LTD.